

FIG. 1




FIG. 2

S11 log MAG 5dB/ REF 0 dB

S21 log MAG 10dB/ REF 0 dB




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

PREPARATION OF TABLE




FIG. 8

<div><div>a1</div><div>a2</div></div>	x0 [mm]	x1 [mm]	x2 [mm]
yo [mm]	CHAR·A	CHAR·B	CHAR·C
y1 [mm]	CHAR·D	CHAR·E	CHAR·F
y2 [mm]	CHAR·G	CHAR·H	CHAR·I

CHAR = CHARACTERISTIC VALUES